

# Indoor air sealing repair of senior apartments | Vaasa



## Description

Sealing repair in connection with the basic repair: Upper floor-wall joint, hollow tile seams, penetrations, window joints and intermediate floor-wall joint.

## Information

The site is a concrete sandwich element (+cavity slab) house, which was built in 1985 as a service building. Currently, the building has senior apartments, service providers and office space.

## Project information

**Client:** Vuorikatu Senior Apartment

**Project:** Indoor Air Sealing

**Address:** Vuorikatu 2-4, Vaasa, Finland

**Material:** Concrete sandwich element

**Contractor:** Drytec Oy

**Supervisor:** Vahanen Rakennusfysiikka Oy, Arto Toorikka

**Time and city:** 07/2020 | Vaasa

## Products used in the project

- [ElaProof Indoor](#)
- [ElaProof Primer](#)
- [ElaProof Base Fabric](#)

