

Balcony waterproofing | Vantaa



Description

There are leaks in the wall-floor boundary on the balcony of a detached house in Vantaa. The base was carefully cleaned and primed with ElaProof Primer. The balcony was carefully sealed using ElaProof Base Fabric and ElaProof H.

Project information

Client: Private house

Project: Balcony waterproofing

Address: Rubiininkhä, Vantaa, Finland

Material: Concrete

Contractor: Laatukodit Uusimaa Oy

Time and city: 06 / 2020 | Vantaa

Products used in the project

- [ElaProof Classic H](#)
- [ElaProof Primer](#)

- [ElaProof Base Fabric](#)

